File   View   Edit   Tools   Window   Help

BRS:
- Pending
- Active
  - L2: (1) 1 and superimposS3
  - L3: (2) 1 and (half-cycle or (half adj cycle))
  - L1: (12) (discharge adj lamp) and (electrode or filamer
  - L4: (51) lamp and (electrode or filament) and (AC or (
  - L5: (9) 4 and superimposS3
  - L6: (11) (discharge adj lamp) and (electrode or filamer
  - L7: (11) 6 and temperature
- Failed
- Saved
- Favorites
- Tagged (0)
- UDC
- Queue
- Trash

Search   List   Browse   Queue   Clear

DBs   US-PGPUB: USPAT: USOCR: FPRS: EPO: JPO: DERWENT: IBM_TDB

☑ Plurals
☑ Highlight all hit terms initially

Default operator: OR

BRS form   IS&R form   Image   Text   HTML

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Er	Erro
1	BRS	L2	1	1 and superimposS3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/08/31 17:23			
2	BRS	L3	2	1 and (half-cycle or (half adj cycle))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/08/31 17:15			
3	BRS	L1	12	(discharge adj lamp) and (electrode or filament) and (AC or (alternating adj current)) and ((DC or (direct adj current)) near2 component) and ((temperature or thermal) near2 compensatS3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/08/31 17:25			
4	BRS	L4	51	lamp and (electrode or filament) and (AC or (alternating adj current)) and ((DC or (direct adj current)) near2 component) and ((temperature or thermal) near2 compensatS3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/08/31 17:23			
5	BRS	L5	9	4 and superimposS3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/08/31 17:23			
6	BRS	L6	11	(discharge adj lamp) and (electrode or filament) and (AC or (alternating adj current)) and (selectS3 near4 (DC or (direct adj current)) near2 component)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/08/31 17:25			
7	BRS	L7	11	6 and temperature	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/08/31 17:26			

Hits   Details   HTML

Ready   SCRL

File View Edit Tools Window Help

- Drafts
- Pending
- Active
  - L1: (1) ((method or process) and operating and (discharg
- Failed
- Saved
- Favorites
- Tagged (0)
- UDC
- Queue
- Trash

Search | List | Browse | Queue | Clear
DBs US-PGPUB
Default operator. OR

☑ Plurals
☑ Highlight all hit terms initially

BRS form | IS&R form | Image | Text | HTML

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Er	Erro
1	BRS	L1	1	((method or process) and operating and (discharge near2 lamp) and electrode and applying and (AC or (alternating adj current)) and (DC or (direct near2 current)) and (temperature near3 compensatS3) and difference and selected and (lower near2 temperature) and anode and cathode).clm.	US-PGPUB	2007/09/04 11:24			

Hits | Details | HTML

Ready